



🔹 Pinellas

13075 US Hwy 19 N
Clearwater, Florida 33764
Phone: (727) 581-9339
Fax: (727) 581-8332

🔹 Sarasota

1595 Barber Road
Sarasota, Florida 34240
Phone: (941) 377-2100
Fax: (941) 377-2001

October 5, 2018

Sent Via Email:
adminlb@tampabay.rr.com

RE: Inspection of: Fire Alarm System
Property: Long Bayou
10039 62nd Terrace N
Clubhouse
St. Petersburg, FL 33708

To Whom It May Concern:

Per the request of the insured, this letter is to confirm that the above referenced property is equipped with a Fire Alarm System. Piper Fire Protection, Inc. inspected this system according to NFPA guidelines on **October 3, 2018**.

For more information on the inspection, please refer to the inspection reports, which can be obtained from the insured or the insured's property manager.

Please be advised that the systems that were tested were active and functional at the time of inspection. Upon completion, the alarm panel was placed back in service. Please note that the inspectors may not have been granted access to all areas of the property, including some living domicile areas, as noted on the report. Piper Fire Protection, Inc. has no knowledge of deficiencies located in either the common or living areas of the building that were not indicated on the report of inspection, and can't comment on areas that we have not been granted access to.

Sincerely,

A handwritten signature in blue ink, appearing to read "Mark Stoefer", written over a blue horizontal line.

Mark Stoefer
Fire Alarm Division Manager

Design • Install • Inspect • Service

Lic. #: EF - 0001219 • Lic. #: 57668600012001 • Lic. #: 392845000622001 • Lic. #: 71286800011990 • Lic. #: 45152300011999

1-800-327-7604 • WWW.PIPERFIRE.COM



RAPID RESPONSE MONITORING

ALARM SYSTEM CERTIFICATE-NO. 8193341

Alabama 99-440 • Florida FF0009864 • Oklahoma 648
Texas B-09580 • Virginia 11-2850



This is to certify that Rapid Response Monitoring is a Factory Mutual approved monitoring a Security System that has been installed at the below address:

Underwriters Laboratories Protective Signaling Services Central Station

Name: Long Bayou Office
Address: 9777 62nd Terrace North
City, State, Zip: Saint Petersburg, FL 33708
Date of Installation: 02/22/2013

The following Protection is provided by the Security Equipment:

- Burglary Protection
- Medical Emergency Protection
- Maintenance Repair Service Agreement
- Fire Protection
- Low Temperature Protection
- No Expiration Date
- Panic/Holdup Protection

The following Special Monitoring Services are provided:

- Long Range One Way Supervised
- Long Range Two Way Supervised
- Direct Wire
- Derived Channel Transmission

Alarm Dealer: _____
Dealer: Piper Fire Protection Name: Mackenzie Shepherd
Address: 13075 US HWY 19 N Authorized Signature: Mackenzie Shepherd
City, State, Zip: Clearwater, FL 33760 Title: Coordination Supervisor Date: 10-1-18



Pinellas

13075 US Hwy 19 N
Clearwater, Florida 33764
Phone: (727) 581-9339
Fax: (727) 581-8332

Sarasota

1595 Barber Road
Sarasota, Florida 34240
Phone: (941) 377-2100
Fax: (941) 377-2001

September 27, 2018

Sent Via Email:
adminib@tampabay.rr.com

RE: Inspection of: Fire Alarm System
Property: Long Bayou
10032 65th Ave N
Building 1
St. Petersburg, FL 33708

To Whom It May Concern:

Per the request of the Insured, this letter is to confirm that the above referenced property is equipped with a Fire Alarm System. Piper Fire Protection, Inc. inspected this system according to NFPA guidelines on August 23, 2018.

For more information on the inspection, please refer to the inspection reports, which can be obtained from the insured or the insured's property manager.

Please be advised that the systems that were tested were active and functional at the time of inspection. Upon completion, the alarm panel was placed back in service. Please note that the Inspectors may not have been granted access to all areas of the property, including some living domicile areas, as noted on the report. Piper Fire Protection, Inc. has no knowledge of deficiencies located in either the common or living areas of the building that were not indicated on the report of inspection, and can't comment on areas that we have not been granted access to.

Sincerely,

A handwritten signature in blue ink, appearing to read "M. Stoesen", is written over a light blue circular stamp.

Mark Stoesen
Fire Alarm Division Manager

Design • Install • Inspect • Service

Lic. #: EF - 0001219 • Lic. #: 57666600012001 • Lic. #: 392845000622001 • Lic. #: 71286800011990 • Lic. #: 45152300011999
1-800-327-7604 • WWW.PIPERFIRE.COM

RAPID RESPONSE  **MONITORING**

ALARM SYSTEM CERTIFICATE-NO. 8193342

Alabama 99-440 • Florida FF0000964 • Oklahoma 648
Texas B-09590 • Virginia 11-2850

This is to certify that Rapid Response Monitoring is a  Factory Mutual approved  Underwriters Laboratories Protective Signalling Services Central Station monitoring a Security System that has been installed at the below address:

Name: Long Bayou Bldg 1
Address: 10032 65th Ave North
City, State, Zip: Saint Petersburg, FL 33708
Date of Installation: 02/22/2013

The following Protection is provided by the Security Equipment:

- Burglary Protection
- Fire Protection
- Medical Emergency Protection
- Maintenance Repair Service Agreement
- Yes No Expiration Date: _____
- Panic/Holdup Protection
- Low Temperature Protection

The following Special Monitoring Services are provided:

- Long Range One Way Supervised
- Long Range Two Way Supervised
- Direct Wire
- Delayed Channel Transmission

Alarm Dealer:
Dealer: Piper Fire Protection
Address: 13075 US HWY 19 N
City, State, Zip: Clearwater, FL 33760

Name: Mackenzie Shepherd
Authorized Signature: Mackenzie Shepherd
Title: Coordination Supervisor
Date: 10-1-18



Pinellas

13075 US Hwy 19 N
Clearwater, Florida 33764
Phone: (727) 581-9339
Fax: (727) 581-8332

Sarasota

1595 Barber Road
Sarasota, Florida 34240
Phone: (941) 377-2100
Fax: (941) 377-2001

September 27, 2018

Sent Via Email:
adminlb@tampabay.rr.com

RE: Inspection of: Fire Alarm System
Property: Long Bayou
10033 64th Ave N
Building 2
St. Petersburg, FL 33708

To Whom It May Concern:

Per the request of the insured, this letter is to confirm that the above referenced property is equipped with a Fire Alarm System. Piper Fire Protection, Inc. inspected this system according to NFPA guidelines on August 23, 2018.

For more information on the inspection, please refer to the inspection reports, which can be obtained from the insured or the insured's property manager.

Please be advised that the systems that were tested were active and functional at the time of inspection. Upon completion, the alarm panel was placed back in service. Please note that the inspectors may not have been granted access to all areas of the property, including some living domicile areas, as noted on the report. Piper Fire Protection, Inc. has no knowledge of deficiencies located in either the common or living areas of the building that were not indicated on the report of inspection, and can't comment on areas that we have not been granted access to.

Sincerely,

A handwritten signature in blue ink, appearing to read "Mark Stoefen", is written over a light blue circular stamp.

Mark Stoefen
Fire Alarm Division Manager

Design • Install • Inspect • Service

Lic. #: EF - 0001219 • Lic. #: 67868800012001 • Lic. #: 392845000622001 • Lic. #: 71286800011990 • Lic. #: 45152300011999
1-800-327-7604 • WWW.PIPERFIRE.COM

RAPID RESPONSE MONITORING

ALARM SYSTEM CERTIFICATE-NO. 8193343

Alabama 99-440 • Florida FF0000964 • Oklahoma 648
Texas B-09690 • Virginia 11-2860

This is to certify that Rapid Response Monitoring is a  Factory Mutual approved  Underwriters Laboratories Protective Signaling Services Central Station monitoring a Security System that has been installed at the below address:

Name: Long Bayou Bldg 2

Address: 10033 64th Ave N

City, State, Zip: Saint Petersburg, FL 33708

Date of Installation: 02/22/2013

The following Protection is provided by the Security Equipment:

- Burglary Protection
- Medical Emergency Protection
- Maintenance Repair Service Agreement
- Long Range One Way Supervised
- Long Range Two Way Supervised
- Fire Protection
- Panic/Holdup Protection
- Low Temperature Protection
- Yes No Expiration Date: _____
- Direct Wire
- Derived Channel Transmission

The following Special Monitoring Services are provided:

Alarm Dealer:

Dealer: Piber Fire Protection

Address: 13075 US HWY 19 N

City, State, Zip: Clearwater, FL 33760

Name: Mackenzie Shepherd

Authorized Signature: Mackenzie Shepherd

Title: Coordination Supervisor Date: 10-1-18



▲ Pinellas

13075 US Hwy 19 N
Clearwater, Florida 33764
Phone: (727) 581-9339
Fax: (727) 581-8332

▲ Sarasota

1595 Barber Road
Sarasota, Florida 34240
Phone: (941) 377-2100
Fax: (941) 377-2001

September 27, 2018

Sent Via Email:
adminlb@tampabay.rr.com

RE: Inspection of: Fire Alarm System
Property: Long Bayou
10034 64th Ave N
Building 3
St. Petersburg, FL 33708

To Whom It May Concern:

Per the request of the insured, this letter is to confirm that the above referenced property is equipped with a Fire Alarm System. Piper Fire Protection, Inc. inspected this system according to NFPA guidelines on August 23, 2018.

For more information on the inspection, please refer to the inspection reports, which can be obtained from the insured or the insured's property manager.

Please be advised that the systems that were tested were active and functional at the time of inspection. Upon completion, the alarm panel was placed back in service. Please note that the inspectors may not have been granted access to all areas of the property, including some living domicile areas, as noted on the report. Piper Fire Protection, Inc. has no knowledge of deficiencies located in either the common or living areas of the building that were not indicated on the report of inspection, and can't comment on areas that we have not been granted access to.

Sincerely,

A handwritten signature in blue ink, appearing to read "M. Stoefen", is written over a horizontal line.

Mark Stoefen
Fire Alarm Division Manager

Design • Install • Inspect • Service

Lic. #: EF-0001219 • Lic. #: 57688600012001 • Lic. #: 392845000622001 • Lic. #: 71286800011990 • Lic. #: 45152300011999
1-800-327-7604 • WWW.PIPERFIRE.COM

RAPID RESPONSE MONITORING

ALARM SYSTEM CERTIFICATE-NO. 8193344

Alabama 99-440 • Florida FF0000984 • Oklahoma 648
Texas B-09690 • Virginia 11-2850

This is to certify that Rapid Response Monitoring is a  Factory Mutual approved  Underwriters Laboratories Protective Signaling Services Central Station monitoring a Security System that has been installed at the below address:

Name: Long Bayou Bldg 3

Address: 10034 64th Ave N

City, State, Zip: Saint Petersburg, FL 33708

Date of Installation: 02/22/2013

The following Protection is provided by the Security Equipment:

- Burglary Protection
- Fire Protection
- Medical Emergency Protection
- Maintenance Repair Service Agreement
- Yes No
- Panic/Holdup Protection
- Low Temperature Protection
- Expiration Date: _____

The following Special Monitoring Services are provided:

- Long Range One Way Supervised
- Long Range Two Way Supervised
- Direct Wire
- Derived Channel Transmission

Alarm Dealer:

Dealer: Piber Fire Protection

Address: 13075 US HWY 19 N

City, State, Zip: Clearwater, FL 33760

Name: Mackenzie Shepherd

Authorized Signature: Mackenzie Shepherd

Title: Coordination Supervisor Date: 10-2-18



△ Pinellas

13075 US Hwy 19 N
Clearwater, Florida 33764
Phone: (727) 581-9339
Fax: (727) 581-8332

△ Sarasota

1595 Barber Road
Sarasota, Florida 34240
Phone: (941) 377-2100
Fax: (941) 377-2001

September 27, 2018

Sent Via Email:
adminlb@tampabay.rr.com

RE: Inspection of: Fire Alarm System
Property: Long Bayou
10035 64th Ave N
Building 4
St. Petersburg, FL 33708

To Whom It May Concern:

Per the request of the insured, this letter is to confirm that the above referenced property is equipped with a Fire Alarm System. Piper Fire Protection, Inc. inspected this system according to NFPA guidelines on August 23, 2018.

For more information on the inspection, please refer to the inspection reports, which can be obtained from the insured or the insured's property manager.

Please be advised that the systems that were tested were active and functional at the time of inspection. Upon completion, the alarm panel was placed back in service. Please note that the inspectors may not have been granted access to all areas of the property, including some living domicile areas, as noted on the report. Piper Fire Protection, Inc. has no knowledge of deficiencies located in either the common or living areas of the building that were not indicated on the report of inspection, and can't comment on areas that we have not been granted access to.

Sincerely,

A handwritten signature in blue ink, appearing to read "M. Stoefer", with a long horizontal flourish extending to the right.

Mark Stoefer
Fire Alarm Division Manager

Design • Install • Inspect • Service

Lic. #: EF - 0001219 • Lic. #: 57688600012001 • Lic. #: 392845000622001 • Lic. #: 71288800011990 • Lic. #: 45152300011999
1-800-327-7604 • WWW.PIPERFIRE.COM

RAPID RESPONSE MONITORING

ALARM SYSTEM CERTIFICATE-NO. 8193345

Alabama 99-440 • Florida FF0000984 • Oklahoma 648
Texas B-09590 • Virginia 11-2850

This is to certify that Rapid Response Monitoring is a  Factory Mutual approved  Underwriters Laboratories Protective Signaling Services Central Station monitoring a Security System that has been installed at the below address:

Name: Long Bayou Bldg 4
Address: 10035 63rd Ave N
City, State, Zip: Saint Petersburg, FL 33708
Date of Installation: 02/22/2013

The following Protection is provided by the Security Equipment:

- Burglary Protection
- Fire Protection
- Medical Emergency Protection
- Maintenance Repair Service Agreement
- Yes No Expiration Date: _____
- Panic/Holdup Protection
- Low Temperature Protection
- Long Range One Way Supervised
- Long Range Two Way Supervised
- Direct Wire
- Derived Channel Transmission

The following Special Monitoring Services are provided:

Alarm Dealer: _____
Dealer: Piper Fire Protection
Address: 13075 US HWY 19 N
City, State, Zip: Clearwater, FL 33760

Name: Mackenzie Shepherd
Authorized Signature: Mackenzie Shepherd
Title: Coordination Supervisor
Date: 10-2-18



Pinellas

13075 US Hwy 19 N
Clearwater, Florida 33764
Phone: (727) 581-9339
Fax: (727) 581-8332

Sarasota

1595 Barber Road
Sarasota, Florida 34240
Phone: (941) 377-2100
Fax: (941) 377-2001

September 27, 2018

Sent Via Email:
adminlb@tampabay.rr.com

RE: Inspection of: Fire Alarm System
Property: Long Bayou
10036 64th Ave N
Building 5
St. Petersburg, FL 33708

To Whom It May Concern:

Per the request of the insured, this letter is to confirm that the above referenced property is equipped with a Fire Alarm System. Piper Fire Protection, Inc. inspected this system according to NFPA guidelines on August 23, 2018.

For more information on the inspection, please refer to the inspection reports, which can be obtained from the insured or the insured's property manager.

Please be advised that the systems that were tested were active and functional at the time of inspection. Upon completion, the alarm panel was placed back in service. Please note that the inspectors may not have been granted access to all areas of the property, including some living domicile areas, as noted on the report. Piper Fire Protection, Inc. has no knowledge of deficiencies located in either the common or living areas of the building that were not indicated on the report of inspection, and can't comment on areas that we have not been granted access to.

Sincerely,

A handwritten signature in blue ink, appearing to read "Mark Stoen", written over a light blue grid background.

Mark Stoen
Fire Alarm Division Manager

Design • Install • Inspect • Service

Lic. #: EF - 0001219 • Lic. #: 57868600012001 • Lic. #: 392845000622001 • Lic. #: 71286800011990 • Lic. #: 45152300011999
1-800-327-7604 • WWW.PIPERFIRE.COM

RAPID RESPONSE MONITORING

ALARM SYSTEM CERTIFICATE-NO. 8193346

Alabama 99-440 • Florida FF0000964 • Oklahoma 646
Texas B-09690 • Virginia 11-2850

This is to certify that Rapid Response Monitoring is a  Factory Mutual approved  Underwriters Laboratories Protective Signaling Services Central Station monitoring a Security System that has been installed at the below address:

Name: Long Bayou Bldg 5
Address: 10036 63rd Ave N
City, State, Zip: Saint Petersburg, FL 33708
Date of Installation: 02/22/2013

The following Protection is provided by the Security Equipment:

- Burglary Protection
 - Fire Protection
 - Medical Emergency Protection
 - Maintenance Repair Service Agreement
 - Yes No Expiration Date: _____
 - Panic/Holdup Protection
 - Low Temperature Protection
- The following Special Monitoring Services are provided:
- Long Range One Way Supervised
 - Long Range Two Way Supervised
 - Direct Wire
 - Derived Channel Transmission

Alarm Dealer: _____
Dealer: Piber Fire Protection Name: Mackenzie Shepherd
Address: 13075 US HWY 19 N Authorized Signature: Mackenzie Shepherd
City, State, Zip: Clearwater, FL 33760 Title: Coordination Supervisor Date: 10-2-18



Pinellas

13075 US Hwy 19 N
Clearwater, Florida 33764
Phone: (727) 581-9339
Fax: (727) 581-8332

Sarasota

1595 Barber Road
Sarasota, Florida 34240
Phone: (941) 377-2100
Fax: (941) 377-2001

September 27, 2018

Sent Via Email:
adminlb@tampabay.rr.com

RE: Inspection of: Fire Alarm System
Property: Long Bayou
10037 64th Ave N
Building 6
St. Petersburg, FL 33708

To Whom It May Concern:

Per the request of the insured, this letter is to confirm that the above referenced property is equipped with a Fire Alarm System. Piper Fire Protection, Inc. inspected this system according to NFPA guidelines on August 23, 2018.

For more information on the inspection, please refer to the inspection reports, which can be obtained from the insured or the insured's property manager.

Please be advised that the systems that were tested were active and functional at the time of inspection. Upon completion, the alarm panel was placed back in service. Please note that the inspectors may not have been granted access to all areas of the property, including some living domicile areas, as noted on the report. Piper Fire Protection, Inc. has no knowledge of deficiencies located in either the common or living areas of the building that were not indicated on the report of inspection, and can't comment on areas that we have not been granted access to.

Sincerely,

A handwritten signature in blue ink, appearing to read "Mark Stofen", is written over a light blue horizontal line.

Mark Stofen
Fire Alarm Division Manager

Design • Install • Inspect • Service

Lic. #: EF - 0001219 • Lic. #: 57668600012001 • Lic. #: 392845000622001 • Lic. #: 71286800011990 • Lic. #: 45152300011999
1-800-327-7604 • WWW.PIPERFIRE.COM

RAPID RESPONSE MONITORING

ALARM SYSTEM CERTIFICATE-NO. 8193347

Alabama 99-440 • Florida FF0000964 • Oklahoma 646
Texas B-09590 • Virginia 11-2850

This is to certify that Rapid Response Monitoring is a  Factory Mutual approved  Underwriters Laboratories Protective Signaling Services Central Station monitoring a Security System that has been installed at the below address:

Name: Long Bayou Bldg 6

Address: 10037 62nd Terrace N

City, State, Zip: Saint Petersburg, FL 33708

Date of Installation: 02/22/2013

The following Protection is provided by the Security Equipment:

- Burglary Protection
- Fire Protection
- Medical Emergency Protection
- Maintenance Repair Service Agreement
- Yes No
- Panic/Holdup Protection
- Low Temperature Protection
- Expiration Date: _____

The following Special Monitoring Services are provided:

- Long Range One Way Supervised
- Long Range Two Way Supervised
- Direct Wire
- Derived Channel Transmission

Alarm Dealer:

Dealer: Piper Fire Protection

Address: 13075 US HWY 19 N

City, State, Zip: Clearwater, FL 33760

Name: Mackenzie Shepherd

Authorized Signature: Mackenzie Shepherd

Title: Coordination Supervisor

Date: 10-2-18



💧 Pinellas

13075 US Hwy 19 N
Clearwater, Florida 33764
Phone: (727) 581-9339
Fax: (727) 581-8332

💧 Sarasota

1595 Barber Road
Sarasota, Florida 34240
Phone: (941) 377-2100
Fax: (941) 377-2001

September 27, 2018

Sent Via Email:

adminlb@tampabay.rr.com

RE: Inspection of: Fire Alarm System
Property: Long Bayou
10038 62nd Terrace N
Building 7
St. Petersburg, FL 33708

To Whom It May Concern:

Per the request of the insured, this letter is to confirm that the above referenced property is equipped with a Fire Alarm System. Piper Fire Protection, Inc. inspected this system according to NFPA guidelines on **August 23, 2018**.

For more information on the inspection, please refer to the inspection reports, which can be obtained from the insured or the insured's property manager.

Please be advised that the systems that were tested were active and functional at the time of inspection. Upon completion, the alarm panel was placed back in service. Please note that the inspectors may not have been granted access to all areas of the property, including some living domicile areas, as noted on the report. Piper Fire Protection, Inc. has no knowledge of deficiencies located in either the common or living areas of the building that were not indicated on the report of inspection, and can't comment on areas that we have not been granted access to.

Sincerely,

A handwritten signature in blue ink, appearing to read "Matt Ahlersmeyer", written in a cursive style.

Matt Ahlersmeyer
Fire Alarm Service Manager

Design • Install • Inspect • Service

Lic. #: EF - 0001219 • Lic. #: 57688600012001 • Lic. #: 392845000622001 • Lic. #: 71286800011990 • Lic. #: 45152300011999

1-800-327-7604 • WWW.PIPERFIRE.COM

RAPID RESPONSE  **MONITORING**

ALARM SYSTEM CERTIFICATE-NO. 8193348

Alabama 99-440 • Florida FFO000964 • Oklahoma 648
Texas B-09590 • Virginia 11-2850

This is to certify that Rapid Response Monitoring is a  Factory Mutual approved  Underwriters Laboratories Protective Signaling Services Central Station monitoring a Security System that has been installed at the below address:

Name: Long Bayou Bldg 7
Address: 10038 62nd Terrace N
City, State, Zip: Saint Petersburg, FL 33708
Date of Installation: 02/22/2013

The following Protection is provided by the Security Equipment:

- Burglary Protection
- Fire Protection
- Medical Emergency Protection
- Maintenance Repair Service Agreement
- Yes No Expiration Date: _____
- Panic/Holdup Protection
- Low Temperature Protection
- Long Range One Way Supervised
- Long Range Two Way Supervised
- Direct Wire
- Derived Channel Transmission

The following Special Monitoring Services are provided:

Alarm Dealer: _____
Dealer: Piper Fire Protection
Address: 13075 US HWY 19 N
City, State, Zip: Clearwater, FL 33760
Name: Mackenzie Shepherd
Authorized Signature: Mackenzie Shepherd
Title: Coordination Supervisor
Date: 10-2-18



♣ Pinellas
13075 US Hwy 19 N
Clearwater, Florida 33764
Phone: (727) 581-9339
Fax: (727) 581-8332

♣ Sarasota
1595 Barber Road
Sarasota, Florida 34240
Phone: (941) 377-2100
Fax: (941) 377-2001

September 27, 2018

Sent Via Email:
adminlb@fampabay.rr.com

RE: Inspection of: Fire Alarm System
Property: Long Bayou
10039 62nd Ave N
Building 8
St. Petersburg, FL 33708

To Whom It May Concern:

Per the request of the insured, this letter is to confirm that the above referenced property is equipped with a Fire Alarm System. Piper Fire Protection, Inc. inspected this system according to NFPA guidelines on August 23, 2018.

For more information on the inspection, please refer to the inspection reports, which can be obtained from the Insured or the Insured's property manager.

Please be advised that the systems that were tested were active and functional at the time of inspection. Upon completion, the alarm panel was placed back in service. Please note that the inspectors may not have been granted access to all areas of the property, including some living domicile areas, as noted on the report. Piper Fire Protection, Inc. has no knowledge of deficiencies located in either the common or living areas of the building that were not indicated on the report of inspection, and can't comment on areas that we have not been granted access to.

Sincerely,

A handwritten signature in blue ink, appearing to read "MS", is written over a light blue horizontal line.

Mark Stoefer
Fire Alarm Division Manager

Design • Install • Inspect • Service

Lic. #: EF - 0001219 • Lic. #: 57888600012001 • Lic. #: 392845000622001 • Lic. #: 71286800011990 • Lic. #: 45152300011999
1-800-327-7804 • WWW.PIPERFIRE.COM

RAPID RESPONSE MONITORING

ALARM SYSTEM CERTIFICATE-NO. 8193349

Alabama 99-440 • Florida FF0000964 • Oklahoma 648
Texas B-09590 • Virginia 11-2850

This is to certify that Rapid Response Monitoring is a  Factory Mutual approved  Underwriters Laboratories Protective Signaling Services Central Station monitoring a Security System that has been installed at the below address:

Name: Long Bayou Bldg 8

Address: 10039 62nd Ave N

City, State, Zip: Saint Petersburg, FL 33708

Date of Installation: 02/22/2013

The following Protection is provided by the Security Equipment:

- Burglary Protection
- Medical Emergency Protection
- Maintenance Repair Service Agreement
- Panic/Holdup Protection
- Low Temperature Protection
- Direct Wire
- Derived Channel Transmission
- Fire Protection
- Yes No
- Long Range One Way Supervised
- Long Range Two Way Supervised
- Expiration Date: _____

The following Special Monitoring Services are provided:

Alarm Dealer:

Dealer: Piper Fire Protection

Address: 13075 US HWY 19 N

City, State, Zip: Clearwater, FL 33760

Name: Mackenzie Shepherd

Authorized Signature: Mackenzie Shepherd

Title: Coordination Supervisor Date: 10-22-18



▲ Pinellas

13075 US Hwy 19 N
Clearwater, Florida 33764
Phone: (727) 581-9339
Fax: (727) 581-8332

▲ Sarasota

1595 Barber Road
Sarasota, Florida 34240
Phone: (941) 377-2100
Fax: (941) 377-2001

September 27, 2018

Sent Via Email:
adminlb@tampabay.rr.com

RE: Inspection of: Fire Alarm System
Property: Long Bayou
10039 62nd Terrace N
Building 9
St. Petersburg, FL 33708

To Whom It May Concern:

Per the request of the insured, this letter is to confirm that the above referenced property is equipped with a Fire Alarm System. Piper Fire Protection, Inc. inspected this system according to NFPA guidelines on August 23, 2018.

For more information on the inspection, please refer to the inspection reports, which can be obtained from the insured or the insured's property manager.

Please be advised that the systems that were tested were active and functional at the time of inspection. Upon completion, the alarm panel was placed back in service. Please note that the inspectors may not have been granted access to all areas of the property, including some living domicile areas, as noted on the report. Piper Fire Protection, Inc. has no knowledge of deficiencies located in either the common or living areas of the building that were not indicated on the report of inspection, and can't comment on areas that we have not been granted access to.

Sincerely,

A handwritten signature in blue ink, appearing to read "M. Stoefer", is written over a light blue horizontal line.

Mark Stoefer
Fire Alarm Division Manager

Design • Install • Inspect • Service

Lic. #: EF - 0001219 • Lic. #: 57668600012001 • Lic. #: 392845000622001 • Lic. #: 71286800011990 • Lic. #: 45152300011999
1-800-327-7604 • WWW.PIPERFIRE.COM

RAPID RESPONSE  **MONITORING**

ALARM SYSTEM CERTIFICATE-NO. 8193350

Alabama 99-440 • Florida FF0000984 • Oklahoma 648
Texas B-09590 • Virginia 11-2850

This is to certify that Rapid Response Monitoring is a  Factory Mutual approved  Underwriters Laboratories Protective Signaling Services Central Station monitoring a Security System that has been installed at the below address:

Name: Long Bayou Bldg 9
Address: 9950 62nd Terrace N
City, State, Zip: Saint Petersburg, FL 33708
Date of Installation: 02/22/2013

The following Protection is provided by the Security Equipment:

- Burglary Protection
- Fire Protection
- Medical Emergency Protection
- Maintenance Repair Service Agreement
- Yes No Expiration Date: _____
- Panic/Holdup Protection
- Low Temperature Protection
- Direct Wire
- Derived Channel Transmission

The following Special Monitoring Services are provided:

- Long Range One Way Supervised
- Long Range Two Way Supervised

Alarm Dealer:
Dealer: Piper Fire Protection
Address: 13075 US HWY 19 N
City, State, Zip: Clearwater, FL 33760

Name: Mackenzie Shepherd
Authorized Signature: Mackenzie Shepherd
Title: Coordination Supervisor
Date: 10-5-18